

Paso Robles – Vine Street 32nd to Caballo Road



Performing infiltration test to determine permeability of existing soil in bore hole (left) and preparing to drill another hole (right)



Boring an infiltration test pit at the shoulder of the road

Looking North on Vine towards Caballo Road

Paso Robles – Vine Street 32nd to Caballo Road



Infiltration test in progress



Infiltration test with drilling rig in background

Looking south on Vine towards Arleen Street