

UNION ROAD IMPROVEMENTS – KLECK TO MONTEBELLO OAKS




Digging footings for Wall No. 1, north side of Union (1/12/15)

UNION ROAD IMPROVEMENTS – KLECK TO MONTEBELLO OAKS



Contractor placing initial backfill material behind Wall No. 2 (1/12/15)

UNION ROAD IMPROVEMENTS – KLECK TO MONTEBELLO OAKS



Crew installing drainage system behind Wall No. 2. (Note that the drainage system consists of pipe surrounded by rocks and wrapped with filter fabric, aka 'burrito' 1/2/15)

