

Paso Robles – DPW 15-11
18th & RIVERSIDE



Concrete cross-gutter east half at 18th & Riverside (1/29/16)

Paso Robles – DPW 15-11
18th & RIVERSIDE



Concrete curb ramps – southeast corner of 18th & Riverside (1/29/16)

Paso Robles – DPW 15-11
18th & RIVERSIDE



Removed & replaced the “uplifted” gutter at 18th east of Riverside, that was impeding flow of runoff (1/29/16)

Paso Robles – DPW 15-11
18th & RIVERSIDE



Patch back paving around the new cross-gutter (east half), at 18th & Riverside (1/29/16)

Debris Clean-Up:
Drainage Pipe at 21st Street

